

**Office of The Sub Division Officer  
PWD Distt. Sub Division No.1, Indore**

S.No. 10)

/SAC/2023

Date: 22/3/24


**BUILDING SAFETY CERTIFICATE**

It is certified that the existing building Shri Devi Ahilya Shishu Vihar (name of the building or premises) at Rajaswagram, Chhatribagh INDORE MP (address) is having block(s)/Floor(s) as per details below:

Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	2	-	-	-	-	-

The building is owned/occupied by Shri Devi Ahilya Shishu Vihar (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of **Sub Divisional Officer PWD Dist. Sub Division No. 1 Indore** (Name of Department/ Govt.) on 22/03/2024 (date of inspection) in the presence of **Principal Ms. Aparna Vyas, Principal of the Institution** (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from 22/03/2024 for a period of 1 years in accordance with rule and subject to compliance of the specific conditions as appended.

Issued on 22/03/2024 at Indore by

  
**Sub Division Officer**  
**PWD Distt. Sub Division No.1, Indore**  
*Sub Divisional Officer*  
P.W.D. (B&R) Dist. Sub Dn. No. 1, INDORE