

**Office of The Sub Division Officer
PWD Distt. Sub Division No.1, Indore**

S.No. 336

/SAC/2026-27

Date : 27/5/26


BUILDING SAFETY CERTIFICATE

It is certified that the existing building **Shri Devi Ahilya Shishu Vihar** at **Rajaswagram, Chhatribagh, Indore (MP)** is having block(s)/Floor(s) as per details below:

Detail of Block(s) in	Block	Block	Block	Block	Block	Block
School	(1)	(2)	(3)	(4)	(5)	(6)
No. of Floor(s) in the Block	G+2					

The building is owned/occupied by **Shri Devi Ahilya Shishu Vihar** have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of **Public Work Department Sub Division No.1, Indore (MP)** (Name of Department/Govt.) on **25/05/2026** (date of inspection) in the presence of **Principal Ms. Aparna Vyas, Chhatribagh, Indore** and that the building/premises is fit for occupancy for running school with effect from 25/05/2026 for a period of 01 years in accordance with rule.

Issued on 25/05/2026 at Indore by Sub Divisional Officer PWD, Indore


Sub Division Officer
2 PWD Distt. Sub Division No.1, Indore
Sub Divisional Officer
P.W.D. (B&R) Dist. Sub Dn. No. 1, INDORE